

Note:

1. Terminal pitch is defined by terminal center to center value.

2. Outer dimension is defined by center lines between scribe lines.