


**Qual Flow Chart for AEC - Q101  
Jumper SOT23 with special wire bonding**



**Notes to Flow Chart**

Burn in / Life Test will test the integrity of Wire & Wire Bonding  
 Parts without silicon die are not be subject to HTRB and HAST test  
 HTRB = High temperature Reverse Bias  
 HAST = High Accelaration Temperature/Humidity Stress Test

**Estimated time for completion of each test :**

LT (96 Hrs) ---- 6 Days  
 Auctocalve (96 Hrs) --- 6 Days  
 RSH (3 Cycles) ---- 2 Days  
 Temperature Cycling (1000 cycles) --102 days